

ZZHY/APJL054

网络信息公开表

存档编号	ZZHY-AP-20200421-055-00		
项目名称	桓仁满族自治县八里甸子镇岱龙江加油站改扩建项目安全设施竣工验收安全评价		
项目类别	验收评价		
项目地点	桓仁满族自治县八里甸子镇岱龙江村		
项目所属业务范围	化工		
评审单位	桓仁满族自治县八里甸子镇岱龙江加油站		
项目简介	桓仁满族自治县八里甸子镇岱龙江加油站位于桓仁满族自治县八里甸子镇岱龙江村，主要经营汽油、柴油。该站原有油品储罐4座，其中2座汽油储罐，容积均为30m ³ ，总容积为60m ³ ；2座柴油储罐，容积均为30m ³ ，总容积为60m ³ ，4台加油机，其中汽油加油机2台，柴油加油机2台。该站根据《国务院关于印发水污染防治行动计划的通知》（国发〔2015〕17号）的要求进行双层罐改造，改造内容包括将油罐改为双层罐，油管改为双层油管。改造后的加油站设30m ³ 汽油埋地SF型双层储罐3座，30m ³ 柴油埋地SF型双层储罐3座，利旧4台加油机，新增2台双枪加油机。		
安全评价项目组长	李守国		
项目技术负责人	姓名	专业	
	刘宝海	—	
项目过程控制负责人	王爽		
评价报告编制人	李万存、李国夫		
评价报告审核人	代瑞锋		
参与评价的安全评价师	姓名	专业	安全评价人员资格证书编号
	李守国	安全	1200000000200105
	李万存	土木	1200000000301532
	鹿传琛	机械	1100000000302276
	李国夫	电气	1100000000301189
	成东	给排水	0800000000303852
参与评价的注册安全工程师	刘宝海、李万存、李国夫		
现场勘查人员	李守国、李万存、李国夫		

现场勘查时间	2020. 3. 5
现场勘查主要任务	确认设计中的安全措施落实情况，企业周边环境，现场安全距离等。
现场勘查照片	 <p>The '现场勘查照片' (Site Inspection Photos) section contains three photographs. The top photograph shows three individuals standing in front of a '龍江石油' (Longjiang Petroleum) station canopy. The bottom-left photograph shows a side view of the station canopy. The bottom-right photograph shows a safety sign with the slogan '早预防于明火 防范胜于' (Prevention is better than fire) and a building in the background.</p>
评价报告提交时间	2020. 05. 25