

## 网络信息公开表

存档编号	LSAP0320200330042-04		
项目名称	中国石油天然气股份有限公司辽宁锦州销售分公司渤海加油站经营危险化学品安全评价报告		
项目类别	安全现状评价		
项目地点	锦州		
项目所属业务范围	石油加工业，化学原料、化学品及医药制造业		
评审单位	锦州市行政审批局		
项目简介	<p>中国石油天然气股份有限公司辽宁锦州销售分公司渤海加油站成立于 2000 年 11 月 2 日，位于凌海市松山镇大木村，为股份有限公司分公司，现在员工 6 人，主要经销汽油、柴油。加油站该站现设潜油泵式加油机 4 台，SF 储油罐 5 座，其中 2 座 30m<sup>3</sup> 汽油储罐，3 座 30m<sup>3</sup> 柴油储罐，柴油罐容积折半计入，计算油罐的总容积为 105m<sup>3</sup>，为二级加油站。</p>		
安全评价项目组长	赵艳艳		
项目技术负责人	姓 名	专 业	
	李强	化工工艺	
项目过程控制负责人	王爽		
评价报告编制人	赵艳艳		
评价报告审核人	王婷		
参与评价的安全评价师	姓 名	专 业	安全评价人员资格证书编号
	赵艳艳	化工工艺	1100000000200181
	邵丹	电气	1100000000200707
	于洁	安全	1800000000300338
	李国夫	自动化	1100000000301189
	陶崇慧	机械	1700000000200313
参与评价的注册安全工程师	赵艳艳		
项目技术专家	赵艳艳		
现场勘查人员	邵丹、于洁、李国夫、陶崇慧、赵艳艳		

现场勘查时间	2020. 4. 3
现场勘查主要任务	收集报告编制资料
现场勘查照片	 <p>The photographs document the site investigation at a Kunlun Petroleum station. The top image shows the entrance area with a red wall and '昆仑好客' (Kunlun Good Guest) signage. The middle image shows the gas station canopy with '中国石油' (China Petroleum) signage and a car at a pump. The bottom image shows four individuals, two in yellow jackets, standing in front of the entrance.</p>
评价报告提交时间	2020. 5. 30